

2003 & 2004 Suzuki Burgman Electrical Recall

Make: SUZUKI

Model: AN400 BURGMAN

Year: 2003

Build Dates: 2002-08-09 to 2004-01-09

NHTSA CAMPAIGN ID Number: 05V372000

Date Owner's Notified: 2005-09-07 Date Received by ODI: 2005-08-29 Date Added to Database: 2005-08-29

Manufacturer's Involved: AMERICAN SUZUKI MOTOR CORP.

Manufacturer's Responsible for the Recall: AMERICAN SUZUKI MOTOR CORP.

Manufacturer Campaign Number: 2082

Component: ELECTRICAL SYSTEM: IGNITION: SWITCH

Potential Number of Units Affected: 5869

Summary: ON CERTAIN SCOOTERS, IF THE IGNITION SWITCH IS NOT FULLY TURNED FROM THE 'OFF' TO THE 'ON' POSITION, THERE MAY BE UNSTABLE CONTACT BETWEEN THE IGNITION SWITCH CONTACTS. THIS CAN CAUSE ARCING IN THE IGNITION SWITCH.

Consequence: HEAT FROM THE ARCING CAN MELT THE INTERNAL SWITCH BASE PLATE. IF THE SCOOTER IS RIDDEN IN THIS CONDITION, THE IGNITION SWITCH MAY FAIL. IF THIS HAPPENS, THE ENGINE WILL STALL, THE LIGHTS WILL GO OUT, AND THE OPERATOR MAY BE UNABLE TO RESTART THE SCOOTER. THIS COULD RESULT IN A CRASH.

Remedy: DEALERS WILL REPLACE THE IGNITION SWITCH TERMINAL CASE ASSEMBLY. THE RECALL BEGAN ON SEPTEMBER 7, 2005. OWNERS SHOULD CONTACT SUZUKI AT 1-800-255-2550.

Report Initiator: MFR Vehicles Report

Notes: CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATIONS AUTO SAFETY HOTLINE AT 1-888-DASH-2-DOT (1-888-327-4236).